United States Of America

Bepartment of Transportation - Federal Abiation Administration

Supplemental Type Certificate

Number SA00285BO

This Certificate issued to

Pro Star Aviation, LLC Manchester Airport 5 Industrial Drive Manchester, NH 03053

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations.

Original Product Type Certificate Number: C37CE

Cessna

Model: 208B

Description of Type Design Change:

Installation of up to six tactical antennas in accordance with Pro Star Aviation Installation Data List 20876-IDL-01, Revision IR, dated April 8 2009, or later FAA-approved revisions.

Limitations and Conditions:

- 1. Instructions for Continued Airworthiness (ICA), Pro Star Document Number 20876-ICA-01, Revision IR, dated February 6, 2009, or later FAA accepted revisions, shall be made available to the operator at the time of installation.
- The FAA has not certified the wiring installation for which these provisions are intended. You must get additional FAA approval to install this equipment. The FAA must evaluate the installation to ensure it complies with the applicable airworthiness standards.

(See continuation sheet 3 of 3)

If the holder agrees to permit another person to use this certificate to alter the product, the holder must give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: February 20, 2008

Date reissued:

Date of issuance: May 1, 2009

Date amended :



By direction of the Administrator

(Signature) Robert G. Mann

Manager

Boston Aircraft Certification Office

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

United States Of America

Department of Transportation - Federal Abiation Administration

Supplemental Type Certificate

(Continuation Sheet)

Number SA00285BO

Date of Issuance: May 1, 2009

Limitations and Conditions (Continued):

- 3. Required structural inspections for compliance with FAR 23.571 are listed in the Airworthiness Limitations section of the ICA Pro Star Document Number 20876-ICA-01, Revision IR, dated February 6, 2009, or later FAA-approved revisions.
- 4. This approval should not be extended to other aircraft of this model on which other previously approved modifications are incorporated unless it is determined by the installer that the interrelationship between this change and any of those other previously approved modifications will produce no adverse affect upon the airworthiness of that airplane.

--END---